


To: McClain-Vanderpool, Lisa[Mcclain-Vanderpool.Lisa@epa.gov]
From: Thomi, Wendy
Sent: Sat 8/8/2015 6:38:42 PM
Subject: Is this correct?



An acidic, yellowish discharge still was leaking out of the Gold King Mine portal, about 60 miles north of Durango (population 17,000), at an estimated rate of about 1,200 gallons a minute, state and federal officials said. EPA crews at the mine were trying to create a large hole to catch the contaminant-laced wastewater and try to clean it before it reaches streams and rivers.

Wendy Thomi, Brownfields Project Manager

U.S. EPA Region 8 Montana Office

10 W. 15th St.

Helena, MT 59626

Phone: 406-457-5037

Fax: 406-457-5056

Please join me at:



www.brownfieldsconference.org
Chicago, IL • September 2-4, 2015

Brownfields Information

<http://www.epa.gov/brownfields>